




Moisture  
Management  
for Masonry

|               |   |
|---------------|---|
| Product:      | <b>MortarNet® with Insect Barrier™ 2.0"</b>   |
| Manufacturer: | <b>Mortar Net Solutions™</b><br>326 Melton Road<br>Burns Harbor, IN 46304<br>(p)- 1-800-664-6638<br>(f)- 1-219-787-5088<br>info@mortarnet.com |

|           |  |
|-----------|--|
| Date:     |  |
| Project : |  |
| Location: |  |

|   |     |
|---|-----|
| <b>Credit MR4.1 and 4.2: Recycled Content</b>             |     |
| Percentage of Post-industrial Recycled Content by Weight: | 9%  |
| Percentage of Post-consumer Recycled Content by Weight:   | 15% |



|   |   |
|---|---|
| <b>Credit MR5.1 and 5.2: Regional Materials</b> |   |
| Final Assembly/Manufacturing Address:           | 326 Melton Road<br>Burns Harbor, IN 46304 |

| Product Composition Material: | Percentage of Material by Weight: | Manufacturing Location:    |
|-------------------------------|-----------------------------------|----------------------------|
| Polyester Fiber               | 50%                               | Columbia, SC (Richland)    |
| Water-borne Polymer           | 47.7%                             | Cleveland, OH (Cuyahoga)   |
| Spunbond                      | 2.3%                              | Old Hickory, TN (Davidson) |

**Notes:**

<sup>1</sup> Pre-Consumer recycled content previously referred to as post-industrial